

INSTALL TEE ON PIPE WITH AT LEAST 10 PIPE DIAMETERS OF STRAIGHT PIPE UPSTREAM AND 5 PIPE DIAMETERS OF STRAIGHT PIPE DOWNSTREAM OF THE SENSOR.

(1)

N.T.S.

CST BRASS TEE MOUNT FLOW SENSOR INSTALLATION